Test Report

Niviuk Kode P 22 | 170640

Equipment	Niviuk Kode P 22 | 170640
Service	Passed
Rating	Used, good conditions
Comment	EP032N
Date	21. October 2026
Next Service	October 2028 or after 100 flight hours
Service Center	Eagles Service di Di Ciano Lavinia | Checker: Lavinia Di Ciano

Service Steps

- Porosity Test
- Fabric Tear Resistance
- Visual Inspection: Canopy
- Visual Inspection: Lines
- Visual Inspection: Risers

Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

This service was performed using the WingSolution check software.
Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.

https://www.wing-solution.com/en/paraglider-services/protocol/0c4660d1-add6-4596-96bd-09875baa9051

Porosity Test

Gauge	HELLO
1. Measurement	305 [s]
Rating	**Passed**

Fabric Tear Resistance

Bettsometertest	**Passed**

Visual Inspection: Canopy

Rods	Passed
Loops	Passed
Topsail	Passed
Cell walls	Passed
Lower sail	Passed
Leading edge	Passed
Rating	**Passed**

Visual Inspection: Lines

Main lines	Passed
Brake lines	Passed
Gallery lines	Passed
Rating	**Passed**

Visual Inspection: Risers

Risers	Passed
Line locks	Passed
Speed system	Passed
Rating	**Passed**