Test Report

Skywalk X-Alps 5 105+ | 0822-36485

Equipment	Skywalk X-Alps 5 105+ | 0822-36485 Production Date: July 2022
Service	Passed
Rating	Used, good conditions
Date	18. September 2026
Next Service	September 2028 or after 100 flight hours
Service Center	Eagles Service di Di Ciano Lavinia | Checker: Lavinia Di Ciano

Service Steps	Porosity Test
	Fabric Tear Resistance
	Visual Inspection: Canopy
	Visual Inspection: Lines
	Visual Inspection: Risers
	Linen Tear Strength

Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

This service was performed using the WingSolution check software.
Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.

https://www.wing-solution.com/en/paraglider-services/protocol/457f220c-2025-4d26-9166-fdd0deae5066

Porosity Test

Gauge	HELLO
1. Measurement	> 250 [s]
Comment	porosità molto buona su tutto il BDA
Rating	**Passed**

Fabric Tear Resistance

Bettsometertest	**Passed**

Visual Inspection: Canopy

Rods	Passed
Loops	Passed
Topsail	Passed
Cell walls	Passed
Lower sail	Passed
Leading edge	Passed
Rating	**Passed**

Visual Inspection: Lines

Main lines	Passed
Brake lines	Passed
Gallery lines	Passed
Rating	**Passed**

Visual Inspection: Risers

Risers	Passed
Line locks	Passed
Speed system	Passed
Rating	**Passed**

Linen Tear Strength

Right / AI	Minimum strength: **187 daN** / Measured strength: **256 daN** - Passed
Right / A1	Minimum strength: **126 daN** / Measured strength: **149 daN** - Passed
Rating	**Passed**