Test Report

Skywalk MINT 95 | 1623-46094

Equipment	Skywalk MINT 95 | 1623-46094 Production Date: July 2023
Service	Passed
Rating	Used, good conditions
Comment	EP026B
Date	13. October 2026
Service Center	Eagles Service di Di Ciano Lavinia | Checker: Lavinia Di Ciano

Service Steps	Porosity Test
	Fabric Tear Resistance
	Visual Inspection: Canopy
	Visual Inspection: Lines
	Visual Inspection: Risers

Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

This service was performed using the WingSolution check software.
Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.

https://www.wing-solution.com/en/paraglider-services/protocol/a41d86e6-559f-43b9-98d1-eda7a1534a37

Porosity Test

Gauge	HELLO
1. Measurement	> 250 [s]
Rating	**Passed**

Fabric Tear Resistance

Bettsometertest	**Passed**

Visual Inspection: Canopy

Rods	Passed
Loops	Passed
Topsail	Passed
Cell walls	Passed
Lower sail	Passed
Leading edge	Passed
Rating	**Passed**

Visual Inspection: Lines

Main lines	Passed
Brake lines	Passed
Gallery lines	Passed
Rating	**Passed**

Visual Inspection: Risers

Risers	Passed
Line locks	Passed
Speed system	Passed
Rating	**Passed**