

Test Report

Skywalk Chili 5 S | 31635

wingSOLUTION

Equipment

Skywalk Chili 5 S | 31635
Production Date: October 2021



Service

Passed

Comment

EP001E

Date

27. October 2026

Next Service

October 2028

Service Center

Eagles Service di Di Ciano Lavinia | Checker: Lavinia Di Ciano

Service Steps

Porosity Test

Fabric Tear Resistance

Visual Inspection: Canopy

Visual Inspection: Lines

Visual Inspection: Risers

Linen Tear Strength

Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

wingSOLUTION

This service was performed using the WingSolution check software. Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.



<https://www.wing-solution.com/en/paraglider-services/protocol/:9da0990-0112-4b43-ba30-49b811e22f65>

Porosity Test

Gauge	HELLO
1. Measurement	110 [s]
2. Measurement	139 [s]
Rating	Passed

Fabric Tear Resistance

Bettsometertest	Passed
-----------------	---------------

Visual Inspection: Canopy

Rods	Passed
Loops	Passed
Topsail	Passed
Cell walls	Passed
Lower sail	Passed
Leading edge	Passed
Rating	Passed

Visual Inspection: Lines

Main lines	Passed
Brake lines	Passed
Gallery lines	Passed
Rating	Passed

Visual Inspection: Risers

Risers Passed

Line locks Passed

Speed system Passed

Rating Passed

Linen Tear Strength

Left / A1 Minimum strength: **50 daN** / Measured strength: **68 daN** - Passed

Left / a1 Minimum strength: **22 daN** / Measured strength: **28 daN** - Passed

Rating Passed
