

# Test Report

Advance Epsilon 8 25 | 5556P66349

wingSOLUTION

## Equipment

Advance Epsilon 8 25 | 5556P66349

**myCheck48.de**

Wolfgang Hogen

## Service

Passed

## Rating

Used, good conditions

## Date

14. May 2026

## Next Service

May 2028 or after 150 flight hours or 150 Flights

## Service Center

myCheck48.de | Checker: Wolfgang Hogen

## Service Steps

Porosity Test

---

Fabric Tear Resistance

---

Visual Inspection: Canopy

---

Visual Inspection: Lines

---

Visual Inspection: Risers

---

Linen Tear Strength

---

Trimm

---

## Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

wingSOLUTION

This service was performed using the WingSolution check software.

Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.



<https://www.wing-solution.com/en/paraglider-services/protocol/7119161a-dc57-410e-b254-2cc163b11866>

## Porosity Test

Gauge	HELLO
1. Measurement	205 [s]
2. Measurement	186 [s]

**Rating** **Passed**

---

## Fabric Tear Resistance

Bettsometertest **Passed**

---

## Visual Inspection: Canopy

Rods	Passed
Loops	Passed
Topsail	Passed
Cell walls	Passed
Lower sail	Passed
Leading edge	Passed

**Rating** **Passed**

---

## Visual Inspection: Lines

Main lines	Passed	Bei Leine CI links, CIII rechts, AI rechts wurde eine Beschädigung festgestellt. Für diese Leinen wurde ein Ersatz angefertigt und in den Schirm eingebaut.
Brake lines	Passed	Beide Brems- Stammleinen wurden erneuert,
Gallery lines	Passed	

**Rating** **Passed**

---

## Visual Inspection: Risers

Risers Passed

Line locks Passed

Speed system Passed

**Rating Passed**

## Linens Tear Strength

Left / 1A1 Minimum strength: **110 daN** / Measured strength: **133 daN** - Passed

**Rating Passed**

## Trimm

For additional details and a comprehensive graphic, please refer to the online protocol.

### Mainlines

ST	3	2	1		1	2	3	ST
DL	SL	SL	SL	A	SL	SL	SL	SL
	SL	SL	SL	B	SL	SL	SL	
	DL	DL	SL	C	SL	DL	DL	

The left brake line was extended by 23mm.

The right brake line was extended by 21mm.

## Linen Length: Left

A Linen			ST Linen			B Linen			C Linen			D Linen			BR Linen		
Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.
7009	7011	2	6260	6260	0	6904	6905	1	7022	7023	1	7151	7152	1	7409	7394	-15
6946	6948	2	6242	6245	3	6845	6844	-1	6962	6959	-3	7088	7084	-4	7075	7077	2
6882	6883	1	6029	6027	-2	6785	6781	-4	6886	6881	-5	7005	7002	-3	7002	7005	3
6829	6830	1	6071	6064	-7	6740	6735	-5	6832	6828	-4	6939	6934	-5	6784	6797	13
6736	6729	-7	6139	6136	-3	6674	6668	-6	6733	6730	-3	Average		-3	6634	6642	8
6629	6624	-5	6207	6203	-4	6578	6572	-6	6628	6627	-1	Tolerance		(-10,10)	6538	6553	15
6538	6541	3	Average		-2	6493	6496	3	6528	6536	8			6535	6548	13	
6523	6528	5	Tolerance		(-15,10)	6478	6483	5	6511	6518	7			6425	6444	19	
Average		0				Average		-2	Average		0			6303	6318	15	
Tolerance		(-10,10)				Tolerance		(-10,10)	Tolerance		(-10,10)			6243	6262	19	
														6173	6189	16	
												Average				10	
												Tolerance				(-10,50)	

## Linen Length: Right

A Linen			ST Linen			B Linen			C Linen			D Linen			BR Linen		
Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.	Ref.	Act.	Diff.
7009	7006	-3	6260	6265	5	6904	6903	-1	7022	7017	-5	7151	7144	-7	7409	7399	-10
6946	6952	6	6242	6248	6	6845	6845	0	6962	6959	-3	7088	7084	-4	7075	7072	-3
6882	6880	-2	6029	6034	5	6785	6786	1	6886	6885	-1	7005	7003	-2	7002	7008	6
6829	6830	1	6071	6072	1	6740	6737	-3	6832	6833	1	6939	6935	-4	6784	6803	19
6736	6726	-10	6139	6139	0	6674	6670	-4	6733	6725	-8	Average		-4	6634	6646	12
6629	6622	-7	6207	6208	1	6578	6571	-7	6628	6621	-7	Tolerance		(-10,10)	6538	6554	16
6538	6540	2	Average		3	6493	6493	0	6528	6528	0			6535	6553	18	
6523	6524	1	Tolerance		(-15,10)	6478	6478	0	6511	6515	4			6425	6442	17	
Average		-2				Average		-2	Average		-2			6303	6313	10	
Tolerance		(-10,10)				Tolerance		(-10,10)	Tolerance		(-10,10)			6243	6253	10	
														6173	6186	13	
												Average				10	
												Tolerance				(-10,50)	