

Test Report

Swing Axis 5 24 | 44-324-49476

wingSOLUTION

Equipment

Swing Axis 5 24 | 44-324-49476

Production Date: August 2015



Service

Passed

Rating

Used, good conditions

Comment

EP011N

Date

21. October 2026

Next Service

October 2028 or after 100 flight hours

Service Center

Eagles Service di Di Ciano Lavinia | Checker: Lavinia Di Ciano

Service Steps

Porosity Test

Fabric Tear Resistance

Visual Inspection: Canopy

Visual Inspection: Lines

Visual Inspection: Risers

Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

wingSOLUTION

This service was performed using the WingSolution check software. Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.



<https://www.wing-solution.com/en/paraglider-services/protocol/1f86a0cc-7d16-411e-a0de-dc3e93da7a0a>

Porosity Test

Gauge	HELLO
1. Measurement	252 [s]
Rating	Passed

Fabric Tear Resistance

Bettsometer test	Passed
------------------	---------------

Visual Inspection: Canopy

Rods	Passed
Loops	Passed
Topsail	Passed
Cell walls	Passed
Lower sail	Passed
Leading edge	Passed
Rating	Passed

Visual Inspection: Lines

Main lines	Passed
Brake lines	Passed
Gallery lines	Passed
Rating	Passed

Visual Inspection: Risers

Risers Passed

Line locks Passed

Speed system Passed

Rating Passed
