

Test Report

Skywalk Mescal 6 XS | 4621-33837

wingSOLUTION

Equipment

Skywalk Mescal 6 XS | 4621-33837

Production Date: December 2024



Service

Passed

Rating

Used, good conditions

Comment

EP027N

Date

13. October 2026

Service Center

Eagles Service di Di Ciano Lavinia | Checker: Lavinia Di Ciano

Service Steps

Porosity Test

Fabric Tear Resistance

Visual Inspection: Canopy

Visual Inspection: Lines

Visual Inspection: Risers

Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

wingSOLUTION

This service was performed using the WingSolution check software. Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.



<https://www.wing-solution.com/en/paraglider-services/protocol/385978e7-03c5-4ce7-872e-e6e78668d1c6>

Porosity Test

Gauge	HELLO
-------	-------

1. Measurement	215 [s]
----------------	---------

Rating	Passed
---------------	---------------

Fabric Tear Resistance

Bettsometer test	Passed
------------------	---------------

Visual Inspection: Canopy

Rods	Passed
------	--------

Loops	Passed
-------	--------

Topsail	Passed
---------	--------

Cell walls	Passed
------------	--------

Lower sail	Passed
------------	--------

Leading edge	Passed
--------------	--------

Rating	Passed
---------------	---------------

Visual Inspection: Lines

Main lines	Passed
------------	--------

Brake lines	Passed
-------------	--------

Gallery lines	Passed
---------------	--------

Rating	Passed
---------------	---------------

Visual Inspection: Risers

Risers Passed

Line locks Passed

Speed system Passed

Rating Passed
