Test Report

BGD Base 3 S | 1246153A

Equipment	BGD Base 3 S | 1246153A Production Date: February 2025
Service	Passed
Comment	EP006E
Date	03. November 2026
Service Center	Eagles Service di Di Ciano Lavinia | Checker: Lavinia Di Ciano

Service Steps	Porosity Test
	Fabric Tear Resistance
	Visual Inspection: Canopy
	Visual Inspection: Lines
	Visual Inspection: Risers

Notice

Your glider has undergone a service. Before flying, it is essential that you test-inflate and thoroughly check it.

This service was performed using the WingSolution check software.
Scan the QR code or follow the link below to view the full online version of your service protocol, which includes additional details and a range of extra features.

https://www.wing-solution.com/en/paraglider-services/protocol/c5d2e65e-ffe2-431c-8689-6e43ff98c7f5

Porosity Test

Gauge	HELLO
1. Measurement	803 [s]
Rating	**Passed**

Fabric Tear Resistance

Bettsometertest	**Passed**

Visual Inspection: Canopy

Rods	Passed
Loops	Passed
Topsail	Passed
Cell walls	Passed
Lower sail	Passed
Leading edge	Passed
Rating	**Passed**

Visual Inspection: Lines

Main lines	Passed
Brake lines	Passed
Gallery lines	Passed
Rating	**Passed**

Visual Inspection: Risers

Risers	Passed
Line locks	Passed
Speed system	Passed
Rating	**Passed**